

Hardware Notes – Dell

Last updated: February 15, 2007

Intel Processor - Windows 2000 and Windows NT 4.0

[Pro/ENGINEER 2001](#)

[Pro/ENGINEER 2001 – Legacy Support Only](#)

[Pro/INTRALINK Release 3.0](#)

[Pro/MECHANICA 2001](#)

[CDRS 2001](#)

[3DPAINT 2001](#)

Pro/ENGINEER 2001				
Machine	Operating Systems	^b Graphics Hardware	Window Manager	Graphics Software
Precision Workstation 390	Windows XP Professional	NVIDIA FX3450 (driver 8426)	Windows XP	OpenGL Win32 GDI
Precision Workstation 670	Windows 2000 Professional	NVIDIA FX4500 (driver 6.14.10.7081) NVIDIA FX3400 (driver 6.14.10.6194—replaces drivers 6.14.10.6170 and 6.14.10.6562) NVIDIA FX1400 (driver 6.14.10.6720, datecode 2004290 and later) NVIDIA FX1300, (driver 6.14.10.6170, datecode 2001150 and later; driver 6.14.10.6562, datecode 2004090 and later) ATI V3100 (driver 8.083—replaces driver 8.023.1, datecodes 2004410 and later)	Windows 2000	OpenGL Win32 GDI
	Windows XP Professional	NVIDIA FX4500 (driver 6.14.10.7081) NVIDIA FX3400 (driver 6.14.10.6194—replaces driver 6.14.10.6170) NVIDIA FX1400 (driver 6.14.10.6720, datecode 2004290 and later) NVIDIA FX1300 (driver 6.14.10.6170) ATI V3100 (driver 8.083—replaces driver 8.023.1, datecodes 2004410 and later)	Windows XP	OpenGL Win32 GDI
Precision Workstation 470	Windows 2000 Professional	NVIDIA FX3400 (driver 6.14.10.6170) NVIDIA FX1300 (driver 6.14.10.6170) ATI V3100 (driver 8.023.1)	Windows 2000	OpenGL Win32 GDI

Pro/ENGINEER 2001				
Machine	Operating Systems	^b Graphics Hardware	Window Manager	Graphics Software
	Windows XP Professional	NVIDIA FX3400 (driver 6.14.10.6170) NVIDIA FX1300 (driver 6.14.10.6170) ATI V3100 (driver 8.023.1)	Windows XP	OpenGL Win32 GDI
Precision Workstation 370	Windows 2000 Professional	NVIDIA FX1300, driver 6.14.10.6170 (datecodes 2004090 and later) NVIDIA FX1400, driver 6.14.10.6720 (datecodes 2004290 and later) NVIDIA FX3400, driver 6.14.10.6194 (datecodes 2004290 and later) NVIDIA FX4400, driver 6.14.10.7081 (datecodes 2004410 and later) ATI FireGL V3100, driver 8.083 (datecodes 2004290 and later)	Windows 2000	OpenGL Win32 GDI
	Windows XP Professional	NVIDIA FX1300, driver 6.14.10.6170 (datecodes 2004090 and later) NVIDIA FX1400, driver 6.14.10.6720 (datecodes 2004290 and later) NVIDIA FX3400, driver 6.14.10.6194 (datecodes 2004290 and later) NVIDIA FX4400, driver 6.14.10.7081 (datecodes 2004410 and later) ATI FireGL V3100, driver 8.083 (datecodes 2004290 and later)	Windows XP	OpenGL Win32 GDI
Precision Workstation M20 Laptop	Windows 2000 Professional	ATI Mobility FireGL V3100, driver package 8.083 (datecodes 2004290 and later)	Windows 2000	OpenGL Win32 GDI
	Windows XP Professional	ATI Mobility FireGL V3100, driver package 8.083 (datecodes 2004290 and later)	Windows XP	OpenGL Win32 GDI
Precision Workstation M60 Laptop	Windows 2000 Professional	NVIDIA Quadro FX Go1000 (driver 6.14.10.5381) NVIDIA Quadro FX Go700 (driver 6.14.10.4424)	Windows 2000	OpenGL Win32 GDI
	Windows XP Professional	NVIDIA Quadro FX Go1000 (driver 6.14.10.5381) NVIDIA Quadro FX Go700 GoGL (driver 6.14.10.4424)	Windows XP	OpenGL Win32 GDI
Precision Workstation M50 Laptop	Windows 2000 Professional	NVIDIA Quadro4 700 GoGL (driver 6.14.01.4201) NVIDIA Quadro4 500 GoGL (driver 6.13.10.28.35 or 6.13.10.3082)	Windows 2000	OpenGL Win32 GDI
	Windows XP Professional	NVIDIA Quadro4 700 GoGL (driver 6.14.01.4201) NVIDIA Quadro4 500 GoGL (driver 6.13.10.28.35 or 6.13.10.3082)	Windows XP	OpenGL Win32 GDI

Pro/ENGINEER 2001

Machine	Operating Systems	^b Graphics Hardware	Window Manager	Graphics Software
Precision Workstation M40 ^a	Windows 2000 Professional	NVIDIA Quadro 2 Go MXR (driver 5.13.01.1620)	Windows 2000	OpenGL Win32 GDI
Precision Workstation 650	Windows XP Professional	NVIDIA FX3000 (driver 6.14.10.4529) (as of datecode 2003320) 3Dlabs Wildcat 4 7110 (driver 6.6.0.38) NVIDIA FX500 (driver 6.12.10.4354) NVIDIA FX 1000 (driver 6.14.01.4371) NVIDIA Quadro4 900 XGL (driver 6.13.10.3082) ATI Fire GL X1 (driver 6.13.10.1018) ATI Fire GL E1 (driver 6.12.10.3049)	Windows XP	OpenGL Win32 GDI
	Windows 2000 Professional	NVIDIA FX3000 (driver 6.14.10.4529) (as of datecode 2003320) 3Dlabs Wildcat 4 7110 (driver 5.6.0.38) NVIDIA FX500 (driver 6.12.10.4354) NVIDIA FX 1000 (driver 6.14.01.4371) NVIDIA Quadro4 900 XGL (driver 6.13.10.3082) ATI Fire GL X1 (driver 6.13.10.1018) ATI Fire GL E1 (driver 5.12.2195.3049)	Windows 2000	OpenGL Win32 GDI
Precision Workstation 530	Windows 2000 Professional	NVIDIA Quadro4 900 XGL (driver 6.13.10.2880 or 6.13.10.3082) NVIDIA Quadro4 700 XGL (driver 6.13.10.2880 or 6.13.10.3082) 3Dlabs Wildcat III 6110 (driver 5.5.2.9 or 6.5.2.9) 3Dlabs Wildcat II 5110 ATI Fire GL2 (driver 5.12.2195.2070) NVIDIA Quadro2 Pro, Quadro2 EX, GeForce2 GTS (driver 5.12.1.650)	Windows 2000	OpenGL Win32 GDI

Pro/ENGINEER 2001

Machine	Operating Systems	^b Graphics Hardware	Window Manager	Graphics Software
	Windows XP Professional	3Dlabs Wildcat III 6110 (driver 6.5.2.9) NVIDIA Quadro4 900 XGL (driver 6.13.10.2880 or 6.13.10.3082) NVIDIA Quadro4 700 XGL (driver 6.13.10.2880 or 6.13.10.3082)	Windows XP	OpenGL Win32 GDI
	Windows NT 4.0	NVIDIA Quadro4 900 XGL (driver 4.00.1381.2885 or 4.00.1381.3082) NVIDIA Quadro4 700 XGL (driver 4.00.1381.2885 or 6.13.10.3082) 3Dlabs Wildcat III 6110 (driver 4.5.0.16) 3Dlabs Wildcat II 5110 (driver 4.02.02.04) ATI Fire GL2 (driver 4.00.1381.2046) NVIDIA Quadro2 Pro, GeForce2 GTS (driver 4.00.1381.650)	Windows NT 4.0	OpenGL Win32 GDI
Precision Workstation 450	Windows XP Professional	NVIDIA FX3000 (driver 6.14.10.4529) (as of datecode 2003320) NVIDIA FX500 (driver 6.12.10.4354) NVIDIA FX 1000 (driver 6.14.01.4371) NVIDIA Quadro4 900XGL (driver 6.13.10.3082) ATI Fire GL X1 (driver 6.13.10.1018) ATI Fire GL E1 (driver 6.12.10.3049) 3DLabs Wildcat 4 7110 (driver 6.6.0.38)	Windows XP	OpenGL Win32GDI

Pro/ENGINEER 2001

Machine	Operating Systems	Graphics Hardware	Window Manager	Graphics Software
	Windows 2000 Professional	NVIDIA FX3000 (driver 6.14.10.4529) (as of datecode 2003320) NVIDIA FX500 (driver 6.12.10.4354) NVIDIA FX 1000 (driver 6.14.01.4371) NVIDIA Quadro4 900XGL (driver 6.13.10.3082) ATI Fire GL X1 (driver 6.13.10.1018) ATI Fire GL E1 (driver 5.12.2195.3049) 3DLabs Wildcat 4 7110 (driver 5.6.0.38)	Windows 2000	OpenGL Win32GDI
Precision Workstation 620, 420	Windows 2000 Professional	Intense3D Wildcat 4110 Pro Elsa Gloria II Pro, Synergy Force NVIDIA Quadro2 Pro, GeForce2 GTS ATI Fire GL2	Windows 2000	OpenGL Win32GDI
	Windows NT 4.0	ELSA GLoria II Pro, Synergy Force Intense 3D Wildcat 4110 Pro ATI Fire GL1, Fire GL2 Diamond Viper 770 (legacy support only) NVIDIA Quadro2 Pro, GeForce2 GTS	Windows NT 4.0	OpenGL Win32 GDI
Precision Workstation 360	Windows XP	NVIDIA FX3000 (driver 6.14.10.4529) (as of datecode 2003320) NVIDIA FX500 (driver 6.13.10.4354) NVIDIA FX1000 (driver 43.71) ATI FireGL X1 (driver 6.13.10.1018) 3DLabs Wildcatr 7110 (driver 6.6.0.38)	Windows XP	OpenGL Win32GDI

Pro/ENGINEER 2001

Machine	Operating Systems	Graphics Hardware	Window Manager	Graphics Software
	Windows 2000	NVIDIA FX3000 (driver 6.14.10.4529) (as of datecode 2003320) NVIDIA FX500 (driver 6.13.10.4354) NVIDIA FX1000 (driver 43.71) ATI FireGL X1 (driver 6.13.10.1018) 3DLabs Wildcat 7110 (driver 5.6.0.38)	Windows 2000	OpenGL Win32GDI
Precision Workstation 350	Windows XP Professional	NVIDIA Quadro4 900XGL (driver 6.13.10.3082) ATI Fire GL E1 (driver 6.13.10.3049) ATI Fire GL X1 (driver 6.13.10.1018)	Windows XP	OpenGL Win32 GDI
	Windows 2000 Professional	NVIDIA Quadro4 900 XGL (driver 6.13.10.3082) ATI Fire GL X1 (driver 6.13.10.1018) ATI Fire GL E1 (driver 5.12.2195.3049)	Windows 2000	OpenGL Win32GDI
Precision Workstation 340	Windows XP Professional	NVIDIA Quadro4 900XGL (driver 6.13.10.2880 or 6.13.10.3082) NVIDIA Quadro4 700XGL (driver 6.13.10.2880)	Windows XP	OpenGL Win32 GDI
	Windows 2000 Professional	NVIDIA Quadro4 900 XGL (driver 6.13.10.2880) NVIDIA Quadro4 700XGL (driver 6.13.10.2880) NVIDIA Quadro2 Pro (driver 5.13.01.1410) NVIDIA Quadro2 EX (driver 5.13.01.1410) Fire GL2 (driver 5.12.2195.2077)	Windows 2000	OpenGL Win32GDI
	Windows NT 4.0	NVIDIA Quadro4 900XGL (driver 4.00.1381.2885) NVIDIA Quadro4 700XGL (driver 4.00.1381.2885) NVIDIA Quadro2 Pro (driver 4.00.1381.1410) NVIDIA Quadro2 EX (driver 4.00.1381.1410) ATI Fire GL2 (driver 4.00.1381.2077)	Windows NT 4.0	OpenGL Win32GDI

Pro/ENGINEER 2001				
Machine	Operating Systems	^b Graphics Hardware	Window Manager	Graphics Software
Precision Workstation 330	Windows 2000 Professional	NVIDIA Quadro2 Pro (driver 5.12.1.650) GeForce2 GTS 3Dlabs Wildcat II 5110 (driver 5.03.01.11) ATI Fire GL2 (driver 5.12.2195.2070)	Windows 2000	OpenGL Win32GDI
	Windows NT 4.0	NVIDIA Quadro2 Pro (driver 4.0.1381.650) GeForce2 GTS 3Dlabs Wildcat II 5110 (driver 4.02.02.04) ATI Fire GL2 (4.00.1381.2048)	Windows NT 4.0	OpenGL Win32GDI
Precision Workstation 220	Windows 2000 Professional	Elsa Synergy Force NVIDIA GeForce2 GTS	Windows 2000	OpenGL Win32 GDI
	Windows NT 4.0	NVIDIA GeForce2 GTS Diamond Viper 770 (legacy support only) ELSA Synergy Force	Windows NT 4.0	OpenGL Win32 GDI
Precision Workstation 410, 610	Windows NT 4.0	Intense3D Wildcat 4000 Diamond Viper 770 (legacy support only) ATI Fire GL1	Windows NT 4.0	OpenGL Win32 GDI
Inspiron 7000 (Laptop)	Windows NT 4.0	ATI Rage Pro LT	Windows NT 4.0	OpenGL Win32 GDI

NOTES

^aDue to the inherent nature of LCD displays at high resolutions, you may find that Pro/ENGINEER datum planes and parts displayed in wireframe appear to flicker when being rotated. To mitigate the effect, we suggest the following:

- 1) disable datum plane display during rotation. You can do this in Utilities -> Options by setting spin_with_part_entities to "No"
- 2) enable smooth lines. You can do this in View -> Model -> Display -> Lines -> Smooth

You can further reduce the apparent flickering by reducing the display resolution. Reducing the display resolution may appear to result in a minor quantification of color gradients. Thus Pro/ENGINEER's blended background may appear as a stack of slightly differently colored bands rather than as a smoothly varying color gradient. You can disable Pro/ENGINEER's blended background by selecting View -> Display settings -> System Colors -> Uncheck blended background.

^bAll listed driver versions are PTC-certified. Where multiple drivers for a specific graphics card are listed, PTC recommends you install the most recently certified driver.

Pro/ENGINEER 2001 - Legacy support only

Machine	Operating Systems	Graphics Hardware	Window Manager	Graphics Software
---------	-------------------	-------------------	----------------	-------------------

Precision Workstation 410, 610	Windows NT 4.0	Intergraph Intense3D Pro 3410T, 3410GT 3Dlabs Oxygen GMX Evans & Sutherland AccelGalaxy Diamond Permedia 2 8MB AGP	Windows NT 4.0	OpenGL Win32 GDI
Precision Workstation 210	Windows NT 4.0	Diamond Permedia 2 8MB AGP	Windows NT 4.0	OpenGL Win32 GDI
NOTES				

Pro/INTRALINK Release 3.0	
Machine	Operating Systems
Precision Workstations 210, 220, 330, 410, 420, 530, 610, 620	Windows NT 4.0
Inspiron 7000 (Laptop)	Windows NT 4.0
NOTES	

Pro/MECHANICA 2001				
Machine	Operating Systems	Graphics Hardware	Window Manager	Graphics Software
Precision Workstation 650	Windows XP Professional	NVIDIA FX3000 (driver 6.14.10.4529) (as of datecode 2003320) 3Dlabs Wildcat 4 7110 (driver 6.6.0.38) NVIDIA FX500 (driver 6.12.10.4354) NVIDIA FX 1000 (driver 6.14.01.4371) NVIDIA Quadro4 900 XGL (driver 6.13.10.3082) ATI Fire GL X1 (driver 6.13.10.1018) ATI Fire GL E1 (driver 6.12.10.3049)	Windows XP	OpenGL Win32 GDI

Pro/MECHANICA 2001

Machine	Operating Systems	Graphics Hardware	Window Manager	Graphics Software
	Windows 2000 Professional	NVIDIA FX3000 (driver 6.14.10.4529) (as of datecode 2003320) 3DLabs Wildcat 4 7110 (driver 5.6.0.38) NVIDIA FX500 (driver 6.12.10.4354) NVIDIA FX 1000 (driver 6.14.01.4371) NVIDIA Quadro4 900 XGL (driver 6.13.10.3082) ATI Fire GL X1 (driver 6.13.10.1018) ATI Fire GL E1 (driver 5.12.2195.3049)	Windows 2000	OpenGL Win32 GDI
Precision Workstation 530	Windows 2000	NVIDIA Quadro4 900XGL (driver version 2.8.8.4) ATI Fire GL2 3DLabs Wildcat III 6110 (driver 5.5.2.9 or 6.5.2.9)	Windows 2000	Win32 GDI
	Windows XP Professional	3DLabs Wildcat III 6110 (driver 6.5.2.9) NVIDIA Quadro4 900 XGL (driver 6.13.10.2880)	Windows XP	OpenGL Win32 GDI
Precision Workstation 450	Windows XP Professional	NVIDIA FX3000 (driver 6.14.10.4529) (as of datecode 2003320) NVIDIA FX500 (driver 6.12.10.4354) NVIDIA FX 1000 (driver 6.14.01.4371) NVIDIA Quadro4 900XGL (driver 6.13.10.3082) ATI Fire GL X1 (driver 6.13.10.1018) ATI Fire GL E1 (driver 6.12.10.3049) 3DLabs Wildcat 4 7110 (driver 6.6.0.38)	Windows XP	OpenGL Win32GDI

Pro/MECHANICA 2001

Machine	Operating Systems	Graphics Hardware	Window Manager	Graphics Software
	Windows 2000 Professional	NVIDIA FX3000 (driver 6.14.10.4529) (as of datecode 2003320) NVIDIA FX500 (driver 6.12.10.4354) NVIDIA FX 1000 (driver 6.14.01.4371) NVIDIA Quadro4 900XGL (driver 6.13.10.3082) ATI Fire GL X1 (driver 6.13.10.1018) ATI Fire GL E1 (driver 5.12.2195.3049) 3DLabs Wildcat 4 7110 (driver 5.6.0.38)	Windows 2000	OpenGL Win32GDI
Precision Workstation 420, 620	Windows NT 4.0	ELSA GLoria II Pro, Synergy Force Intense 3D Pro 4110 ATI Fire GL1 Diamond Viper 770 (legacy support only)	Windows NT 4.0	OpenGL Win32 GDI
Precision Workstation 360	Windows XP	NVIDIA FX3000 (driver 6.14.10.4529) (as of datecode 2003320) NVIDIA FX500 (driver 6.13.10.4354) NVIDIA FX1000 (driver 43.71) ATI FireGL X1 (driver 6.13.10.1018) 3DLabs Wildcat 7110 (driver 6.6.0.38)	Windows XP	OpenGL Win32GDI
	Windows 2000	NVIDIA FX3000 (driver 6.14.10.4529) (as of datecode 2003320) NVIDIA FX500 (driver 6.13.10.4354) NVIDIA FX1000 (driver 43.71) ATI FireGL X1 (driver 6.13.10.1018) 3DLabs Wildcat 7110 (driver 5.6.0.38)		

Pro/MECHANICA 2001				
Machine	Operating Systems	Graphics Hardware	Window Manager	Graphics Software
Precision Workstation 350	Windows XP Professional	NVIDIA Quadro4 900 XGL (driver 6.13.10.3082) ATI Fire GL X1 (driver 6.13.10.1018) ATI Fire GL E1 (driver 5.12.2195.3049)	Windows XP	OpenGL Win32 GDI
	Windows 2000 Professional	NVIDIA Quadro4 900 XGL (driver 6.13.10.3082) ATI Fire GL X1 (driver 6.13.10.1018) ATI Fire GL E1 (driver 5.12.2195.3049)	Windows 2000	OpenGL Win32GDI
Precision Workstation 340	Windows XP Professional	NVIDIA Quadro4 900XGL (driver 6.13.10.2880)	Windows XP	OpenGL Win32 GDI
	Windows 2000 Professional	NVIDIA Quadro4 900 XGL (driver 6.13.10.2880)	Windows 2000	OpenGL Win32GDI
Precision Workstation 220	Windows NT 4.0	Diamond Viper 770 (legacy support only) ELSA Synergy Force	Windows NT 4.0	OpenGL Win32 GDI
Precision Workstation 410, 610	Windows NT 4.0	Intense3D Wildcat 4000 Intergraph Intense3D Pro 3410T, 3410GT 3Dlabs Oxygen GMX Evans & Sutherland AccelGalaxy Diamond Viper 770 (legacy support only) ATI Fire GL1 Diamond Permedia 2 8MB AGP	Windows NT 4.0	OpenGL Win32 GDI
Precision Workstation 210	Windows NT 4.0	Diamond Permedia 2 8MB AGP	Windows NT 4.0	OpenGL Win32 GDI
NOTES				
Based on general platform support for Pro/MECHANICA (Intel-based PC), PTC expects these configurations to run, although each may not have been specifically tested.				

CDRS 2001				
Machine	Operating Systems	Graphics Hardware	Window Manager	Graphics Software
Precision Laptop M50	Windows 2000 Professional	NVIDIA Quadro4 500 GoGL (driver 6.13.10.27.50)	Windows 2000	OpenGL
	Windows XP Professional	NVIDIA Quadro4 500 GoGL (driver 6.13.10.28.35)	Windows XP	OpenGL

Precision Laptop M40	Windows 2000 Professional	NVIDIA Quadro 2 Go	Windows 2000	OpenGL
Precision Workstation 420, 620	Windows 2000 Professional	ELSA GLoria II Pro Intense3D Wildcat 4110 NVIDIA Quadro2 Pro, GeForce2 GTS ATI Fire GL2	Windows 2000	OpenGL
	Windows NT 4.0	ELSA GLoria II Pro, Synergy Force Intense3D Wildcat 4110 Diamond Viper 770 (legacy support only) NVIDIA Quadro2 Pro, GeForce2 GTS ATI Fire GL 1, Fire GL2	Windows NT 4.0	OpenGL
Precision Workstation 530	Windows 2000 Professional	3DLabs Wildcat II 5110 3DLabs Wildcat III 6110 (driver 5.5.2.9) NVIDIA Quadro2 Pro, Quadro2 EX, GeForce2 GTS NVIDIA Quadro4 700XGL (driver 27.52) NVIDIA Quadro4 900XGL (driver 28.80) ATI Fire GL2	Windows 2000	OpenGL
	Windows NT 4.0	3DLabs Wildcat II 5110 NVIDIA Quadro2 Pro, GeForce2 GTS ATI Fire GL2	Windows NT 4.0	OpenGL
Precision Workstation 340	Windows 2000 Professional	NVIDIA Quadro2 Pro, Quadro2 EX, GeForce2 GTS NVIDIA Quadro4 700XGL (driver 27.52) NVIDIA Quadro4 900XGL (driver 28.80) ATI Fire GL2	Windows 2000	OpenGL
	Windows NT 4.0	3DLabs Wildcat II 5110 NVIDIA Quadro2 Pro, GeForce2 GTS ATI Fire GL2	Windows NT 4.0	OpenGL

Precision Workstation 330	Windows 2000 Professional	NVIDIA Quadro2 Pro, Quadro2 EX, GeForce2 GTS ATI Fire GL2	Windows 2000	OpenGL
	Windows NT 4.0	3DLabs Wildcat II 5110 NVIDIA Quadro2 Pro, GeForce2 GTS ATI Fire GL2	Windows NT 4.0	OpenGL
Precision Workstation 220	Windows NT 4.0	Diamond Viper 770 (legacy support only) ELSA Synergy Force NVIDIA GeForce2 GTS	Windows NT 4.0	OpenGL
Precision Workstation 410, 610	Windows NT 4.0	Diamond Viper 770 (legacy support only) ATI Fire GL1 Intense3D Wildcat 4000 Intergraph Intense3D Pro 3410T, 3410GT 3DLabs Oxygen GMX	Windows NT 4.0	OpenGL
NOTES				

3DPAINT 2001				
Machine	Operating Systems	Graphics Hardware	Window Manager	Graphics Software
Precision Laptop M50	Windows 2000 Professional	NVIDIA Quadro4 500 GoGL (driver 6.13.10.27.50)	Windows 2000	OpenGL
	Windows XP Professional	NVIDIA Quadro4 500 GoGL (driver 6.13.10.28.35)	Windows XP	OpenGL
Precision Workstation 420, 620	Windows 2000 Professional	ELSA GLoria II Pro Intense3D Wildcat 4110 NVIDIA Quadro2 Pro ATI Fire GL2	Windows 2000	OpenGL
	Windows NT 4.0	ELSA GLoria II Pro Intense3D Wildcat 4110 NVIDIA Quadro2 Pro ATI Fire GL1, GL2	Windows NT 4.0	OpenGL

Precision Workstation 530	Windows 2000 Professional	3DLabs Wildcat II 5110 3DLabs Wildcat III 6110 (driver 5.5.2.9) NVIDIA Quadro2 Pro, Quadro2 EX, GeForce2 GTS NVIDIA Quadro4 700XGL (driver 27.52) NVIDIA Quadro4 900XGL (driver 28.80) ATI Fire GL2	Windows 2000	OpenGL
	Windows NT 4.0	3DLabs Wildcat II 5110 NVIDIA Quadro2 Pro, GeForce2 GTS ATI Fire GL2	Windows NT 4.0	OpenGL
Precision Workstation 340	Windows 2000 Professional	NVIDIA Quadro2 Pro, Quadro2 EX, GeForce2 GTS NVIDIA Quadro4 700XGL (driver 27.52) NVIDIA Quadro4 900XGL (driver 28.80) ATI Fire GL2	Windows 2000	OpenGL
	Windows NT 4.0	3DLabs Wildcat II 5110 NVIDIA Quadro2 Pro, GeForce2 GTS ATI Fire GL2	Windows NT 4.0	OpenGL
Precision Workstation 330	Windows 2000 Professional	3DLabs Wildcat II 5110 NVIDIA Quadro2 Pro ATI Fire GL2	Windows 2000	OpenGL
	Windows NT 4.0	3DLabs Wildcat II 5110 NVIDIA Quadro2 Pro ATI Fire GL2	Windows NT 4.0	OpenGL
Precision Workstation 410, 610	Windows NT 4.0	ATI Fire GL1 Intense3D Wildcat 4000 Intergraph Intense3D Pro 3410T, 3410GT 3DLabs Oxygen GMX	Windows NT 4.0	OpenGL

NOTES